

Innova Tool – Code Update Instructions

INTRODUCTION

These instructions provide the procedure for updating the firmware on your Innova tool using the Upgrade and CVN codes through the RepairSolutions® software.

MINIMUM SYSTEM REQUIREMENTS

Windows®


- Windows 7, Windows 8.1 or Windows 10
- 16GB Disk Space
- 2GB RAM
- 1.0 GHz Intel or AMD Processor
- 1 USB Port
- Internet Connection



Macintosh®


- OSX 10.10.X and Newer
- 8GB Disk Space
- 2GB RAM
- 1.1 GHz Dual-Core Intel
- 1 USB Port
- Internet Connection

UPDATE INSTRUCTIONS


1. Establish a connection to the internet.
2. Go to: <https://www.innova.com/en-US/Support/Download> to download the latest version of the RepairSolutions® software.
3. Launch the RepairSolutions® software on your computer.
4. Connect the tool to the computer using a USB cable.
5. If the following prompt appears, click YES to get the codes.




6. If the above prompt does not appear, click the Hidden Icons  and right click on the RS icon .
 - a. Click the **Upgrade** section and select **Vehicle Coverage Upgrade** to get the codes.



7. Once the codes are ready, right click on the RS icon once again and select **Enter Upgrade Code**.



8. Enter the Upgrade & CVN codes into their respective fields and click **Upgrade**.



9. Wait until the process completes 100% and the prompt closes.
 - a. If the prompt does not close automatically, you may close it manually once it reads "Updating database... 100% completed".